



APPLICATION GUIDE



WINDSOR MEASURING TAPE SPARE PARTS LIST

<u>Part #</u>	<u>Description</u>	<u>Std. Pack</u>
2149	Hinge Connector	10
2150	Rubber Stop	10
2156	Rivet	100
2157	Plastic Leader	10
2102	Spring Release Hook	10
2610	15m. Tape Refill with Drum	1
2612	50ft. Tape Refill with Drum	1
2634	Main Spring Housing	1
2637	Gear Housing Complete	1
2647	Locking Screw	10

